


Draft 3/27/12

Pavillion Area

Groundwater and/or Soil Impacts at Production Pits



Legend

- All EPA Sampled Well Locations
- ⊕ Pit Monitor Well
- ⊕ EPA Monitoring Wells
- Pits Evaluated by DEQ/VRP**
 - No Known Impact; Groundwater Not Sampled
 - Groundwater DRO Below Cleanup Level
 - Groundwater Impacted (TP 21-9 not confirmed)
 - Impacted Soil > 1000 mg/kg TPH DRO
 - Impacted Soil > 1000 mg/kg TPH DRO and Groundwater DRO Below Cleanup Level
 - Impacted Soil > 1000 mg/kg TPH DRO and Groundwater Impacted
- Detection at Sampled Domestic Well**
 - TPH
 - TPH and VOC's
- Land Rights**
 - ▨ Federal Surface; Tribal Mineral
 - ▨ Private Surface; Tribal Mineral
 - ▨ Federal Surface and Mineral
 - ▨ Private Surface and Mineral

References:

- Well Location Data - Encana Database (maintained by AECOM)
Exported 1/6/2012
- Well Specifications - EPA (Pavillion_EPA_CBL_Evaluation on
66_Prod_Wells_10-4-10(1)2)
- Chemical Analysis - EPA (2012_01-13_Sum All EPA
Data_Pavillion 2009-2011)
- Pit Data - DEQ (Production Pit Info 022312)

NAD 83 UTM Zone 12N
Transverse Mercator

0 0.25 0.5 1
Miles



EPAPAV0000701